


INSTALLATION INSTRUCTIONS

Model 091-64-XX Voltage Indicator

The Model 091-64-XX indicator is a suppressed zero voltmeter which provides an indication of system voltage. Available for 12 or 24 volt systems.

To Mount the 091-64-XX:

1. Cut a 2 inch diameter hole in panel of vehicle.
2. Remove the mounting bracket from the meter.
3. Install meter in panel.
4. Slip mounting bracket over studs of the back of the meter.
5. Fasten meter by installing 2 hex nuts to hold mounting bracket in place.
6. Install wires (see wiring diagram).



SINCE 1967, DESIGNERS OF INNOVATIVE PRODUCTS

KUSSMAUL ELECTRONICS COMPANY, INC.

170 CHERRY AVENUE, WEST SAYVILLE, NEW YORK, 11796-1221 USA

TEL. In NY: 631 567-0314

TOLL FREE: 800 346-0857

FAX: 631 567-5826